

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Problem Image Mailbox.**

Derrick Samuels  
286-453-3638  
10/17

# SMART PEN

Touch sensor Activated  
(Top Removal)





Fig. 1

Derrick Samuel S  
256-453-3638  
2084



Derrick Samuels  
206-4153-3638  
3047




Fig 3

0 DERRICK SAMUELS  
256-453-3638  
40F7




Fig. 4





Fig. 5

# Smart Pen

EXAMPLE: Scan Punctuation Marks



EXAMPLE: Common Names




Fig 6.

Derrick Samuels  
256-453-3638  
#087

SMART PEN




Fig 7.